



Technical Service
BULLETIN

December 12, 1997

Title:

5S-FE ECM TAU FUEL CUT LOGIC CHANGED

Models:

'96 Camry, '96-'97 Celica

ENGINE
EG009-97

Introduction

To improve engine operating smoothness when driving on downhill grades, the engine ECM program logic has been changed.

Affected Vehicles

- **1996** model year **Camrys** and **1996–1997** model year **Celicas** with **5S-FE** engine and **manual transmission**.

Parts Information

OLD PART NUMBER	NEW PART NUMBER	NEW PART NAME & APPLICATION
89661-33730 89661-33731	89661-33732	ECM, CAMRY, MTM, FED. SPEC.
89661-33750 89661-33751	89661-33752	ECM, CAMRY, MTM, CAL. SPEC.
89661-2D290 89661-2D690 89661-2D691	89661-2D692	ECM, CELICA, MTM, FED. SPEC.
89661-2D711	89661-2D712	ECM, CELICA, MTM, CAL. SPEC.

- New parts **may** be used on previous vehicles. Old parts **cannot** be used on newer vehicles.

Warranty Information

OP CODE	VWC	MODEL	DESCRIPTION	TIME	OPN	T1	T2
895011	N	1996 Camry	R&R Engine Control Module	0.6	89661-337#0	03	99
		96-97 Celica		1.1	89661-2D###		

Applicable Warranty:

This repair is covered under the Toyota Powertrain Warranty. This warranty is in effect for 60 months or 60,000 miles, whichever occurs first, from the vehicle's in-service date.

