





iPod Connector Diagnostic Manual

2006 MY SCION PREMIUM AUDIO HEAD UNIT with iPod $^{\rm TM}$ CONTROL TROUBLESHOOTING GUIDE

HINT:

This inspection procedure is a simple troubleshooting procedure. It should be carried out on the vehicle during system operation and was prepared on the assumption of system component troubles (except for the wires and connectors, etc.).

Troubleshooting considerations:


- *Open or short circuit of the wire harness
- *Faulty connector or terminal connection


CARE OF REPLACEMENT PART

When replacing the internal mechanism of the audio system, be careful that no part of your body or clothing comes in contact with the terminals or the leads from any replacement parts.

	Problem	No.
General	No power.	1
	Speakers do not work.	2
iPod control	Poor sound quality.	3
	iPod connected, but cannot select iPod mode.	4
	Head unit cannot turn on the iPod.	5

Issue: A 05/19/05 Page 2 of 6 Pages





Page 4 of 6 Pages

