

TOYOTA TECHNICAL SERVICE BULLETIN


REF.: PRODUCT GENERAL INFORMATION
 NO.: PG001-96
 DATE: JANUARY 26, 1996
 MODEL: ALL MODELS

1996 TECHNICAL SERVICE BULLETIN AND BINDERS

Page 1 of 1

Toyota Technical Service Bulletins (TSBs) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps:

- All 1995 Technical Service Bulletins should be relocated to a temporary binder.
- Place this bulletin along with all 1996 bulletins into the emptied TSB binder.
- During the month of March, all dealers will receive bound books containing all TSBs issued in 1995. Upon receipt, discard all 1995 bulletins and refer only to the bound book for reference.
- Additional copies of 1994 through 1996 TSBs are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM System) by using the following Part Number designation:



RELATED TSB PART NUMBERS:

MATERIAL DESCRIPTION	PART NUMBER
1996 TSB Binder complete with all bulletins issued to date	TSB96*
New TSB Binder and tabs only	00406-61012
1995 TSB Bound Book	00401-43055*
1994 TSB Bound Book	00401-43037

*Available in March, 1996

If you have any questions concerning Toyota Technical Service Bulletins, please contact your District Service Manager.